

ALPHA

PAL14 Installation Guide



Oct,2001

X001ZF0Y-01


the Socket cam box.

the cam box side of the CPU socket.

components that would otherwise interfere with the heat sink.  
- If the heat sink is interfering with motherboard components, try installing the clip in the other set of channels.



do not use excessive force. Make sure the clip is installed correctly on socket tab.



**STEP 4** Final assembly inspection:

Prior to powering up the CPU, visually inspect the heatsink to ensure it is sitting level on the CPU.

Ensure that the heat sink base is only making contact with the CPU die, not the socket cam box or lever arm.