

The FLG462 mounting bracket is not compatible with the base of the PAL8045 due to differences in the machined features. The screw heads present on FLG462 and FLG462-A interfere with the PAL8045's base. This interference prevents proper contact between the processor and heat sink. Naturally, this would damage the processor. The shaded sections of the above figure show the approximate interference points with the PAL8045. Please feel free to contact us with any questions regarding this issue.

